



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	good, getting faded		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PUMP JACK		
Comment:	safety guards		
Corrective Action:		Date:	
Type	OTHER		
Comment:	electric panel, metal panels		
Corrective Action:		Date:	

**Equipment:**

Type	Equipment	Count	Comment	Corrective Action	Date	corrective date
Type: Prime Mover		# 1	Comment: electric motor			
Corrective Action:					Date:	
Type: Pump Jack		# 1				
Comment:						
Corrective Action:					Date:	
Type: Bradenhead		# 1	Comment: pipe to surface			
Corrective Action:					Date:	
Type: Ancillary equipment		# 1	Comment: electric disconnect panel			
Corrective Action:					Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 203332 Type: WELL API Number: 001-08841 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: FLOWLINE AVAILABLE-CONNECTED

Comment: "Well was found in state of Temporary Abandonment.  
Well is overdue for Mechanical Integrity Test (MIT) MIT require 10 day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to plug well. Well can only be returned to SI status if it has produced (without mechanic intervention) within 2 years per Rule 319.b.  
" Valves appeared to be closed at time of inspection

Corrective Action: **Perform successful mechanical integrity test. If a successful MIT can not be performed within 30 day CA time the well must be plugged within 3 months per Rule 417 and 210.** Date: 04/08/2024

**BradenHead**

Date of Last Brhd Test: 06/08/2023 Annual Brhd Completed? Yes  
Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_  
End Surf Csg Pressure: 0

Comment: \_\_\_\_\_  
Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><a href="#">ECMC Inspection Report Summary</a> Inspector Michael Kester, conducted an on-site inspection. Location: John Weigandt B 1 Operator: KPK API#: 123-08841 County: Weld</p> <p>While there, I observed well site with pumping unit During this inspection, the following possible compliance issues were observed: Mechanical integrity Testing Temporarily Abandoned Wells, Rule417c, corrective action date 4-8-2024</p> <p>Weather conditions: over cast and dry A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules. This is a summary of inspection report.</p> <p>This inspection does not nullify any orders or NOAV from the ECMC This is a continuing education inspection</p>	kesterm	03/05/2024

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713300656	site pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6458968">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6458968</a>