



**Location**

Overall Good:

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             | good, rustyand faded |       |  |
| Corrective Action:   |                      | Date: |  |

|                           |                      |  |             |
|---------------------------|----------------------|--|-------------|
| Emergency Contact Number: |                      |  |             |
| Comment:                  | <input type="text"/> |  |             |
| Corrective Action:        | <input type="text"/> |  | Date: _____ |

Overall Good:

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

Multiple Spills and Releases?

|                    |                                   |       |  |
|--------------------|-----------------------------------|-------|--|
| <b>Fencing/:</b>   |                                   |       |  |
| Type               | OTHER                             |       |  |
| Comment:           | electric disconnect, metal panels |       |  |
| Corrective Action: |                                   | Date: |  |
| Type               | PUMP JACK                         |       |  |
| Comment:           | safety guards                     |       |  |
| Corrective Action: |                                   | Date: |  |

|                           |  |       |                 |
|---------------------------|--|-------|-----------------|
| <b>Equipment:</b>         |  |       | corrective date |
| Type: Pump Jack           | # 1  |       |                 |
| Comment:                  |  |       |                 |
| Corrective Action:        |  | Date: |                 |
| Type: Prime Mover         | # 1  |       |                 |
| Comment:                  | electrical motor                           |       |                 |
| Corrective Action:        |  | Date: |                 |
| Type: Bradenhead          | # 1  |       |                 |
| Comment:                  | piped to surface                           |       |                 |
| Corrective Action:        |  | Date: |                 |
| Type: Ancillary equipment | # 3  |       |                 |
| Comment:                  | elctrical disconnect and automation panels |       |                 |
| Corrective Action:        |  | Date: |                 |

|                    |    |       |  |
|--------------------|----|-------|--|
| <b>Venting:</b>    |    |       |  |
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| <b>Flaring:</b>    |  |       |  |
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**

Facility ID: 241142 Type: WELL API Number: 123-08930 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: FLOWLINE AVAILABLE-CONNECTED

**Comment:** Well was found in state of Temporary Abandonment. Well is overdue for Mechanical Integrity Test (MIT) MIT require 10 day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to plug well. Well can only be returned to SI status if it has produced (without mechanic intervention) within 2 years per Rule 319.b. Valves appeared to be closed at time of inspection

**Corrective Action:** Perform successful mechanical integrity test. If a successful MIT can not be performed within 30 day CA time the well must be plugged within 3 months per Rule 417 and 210. **Date:** 04/08/2024

**BradenHead**

Date of Last Brhd Test: 08/03/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

**Comment:** \_\_\_\_\_

**Corrective Action:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**COGCC Comments**

| Comment  | User    | Date       |
|--|---------|------------|
| <p>ECMC Inspection Report Summary<br/>                     Inspector Michael Kester, conducted an on-site inspection.<br/>                     Location: Yoxall Farms 4<br/>                     Operator: KPK<br/>                     API#: 123-08930<br/>                     County: Weld<br/>                     While there, I observed well site with pumping unit<br/>                     During this inspection, the following possible compliance issues were observed:<br/>                     Mechanical integrity Testing Temporarily Abandoned Wells, Rule417c, corrective action date 4-8-2024</p> <p>Weather conditions: over cast and dry<br/>                     A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.<br/>                     This is a summary of inspection report.</p> <p>This inspection does not nullify any orders or NOAV from the ECMC<br/>                     This is a continuing education inspection</p> | kesterm | 03/07/2024 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 713300673    | site pic    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6458977">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6458977</a> |