

# Inspection Photos

3/06/2024

**Operator:** TEP ROCKY MOUNTAIN LLC #96850

**Location ID:** 322438

**Inspection Doc:** 696205669

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 322438



**Photo 1:** Photos taken from the west end of the Location. Photos provide an overview of the Location from east to southeast. Photos examples showing Stormwater and erosion control BMPs remain missing or insufficient; working pad surface lacks stabilization; tracking and erosion degradation observed.



**COLORADO**

**Energy & Carbon Management  
Commission**


Department of Natural Resources



Inspection P  
Operator Name: TEP ROCKY M  
Location ID:



**Photo 2:** Photos right from the 4/25/2023 inspection #708900354, and show erosion degradation and tracking at the working pad surface. Photo left taken 3/6/2024 taken from the same area as photos right, and show BMPs to stabilize the working pad surface had not been installed or maintained; degradation and tracking has persisted.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 322438



**Photo 3:** Photo taken from the edge of the working pad surface on the south end of the Location. Photos show operator has implemented rip-rap material within areas where stormwater runoff is resulting in erosion degradation; outlet has not been installed per good engineering practices or maintained in proper functioning condition; erosion degradation has persisted in these areas.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources