

# Final Reclamation Inspection

March 6th, 2024

Operator: Benson Montin and Greer Drilling Corporation - 7650

Location ID: 325330

Inspection Document #: 714000519

La Plata County, CO

Township: NWNW 10 33N 10W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Ute 6  
Location ID: 325330



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 1.** Overview of the project area taken from the southern edge facing northwest.

API #: 067-06175

Inspection Photos  
Location Name: Ute 6  
Location ID: 325330



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 2.** Cardinal photos taken from the center of the project area. Left photo facing north, right photo facing east.

API #: 067-06175

Inspection Photos  
Location Name: Ute 6  
Location ID: 325330



**Photo 3.** Cardinal photos taken from the center of the project area. Left photo facing south, right photo facing west. Note: Sparse vegetation at the well pad.

Inspection Photos  
Location Name: Ute 6  
Location ID: 325330



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** Rill erosion forming on the southern edge cut slope. Current stormwater BMPs are not functioning properly. Additional stabilization is needed in this area.

API #: 067-06175

Inspection Photos  
Location Name: Ute 6  
Location ID: 325330



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 5.** View of additional rill/gully erosion forming at the access point.

API #: 067-06175

Inspection Photos  
Location Name: Ute 6  
Location ID: 325330



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 6.** View of reference area comprised of smooth brome, rabbit brush, sagebrush and juniper.

API #: 067-06175