

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SNYDER C Pad

Location ID: 336021



Photo # 8622 From entrance to location



Photo # 8623 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SNYDER C Pad

Location ID: 336021



Photo # 8624 Location



Photo # 8625 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SNYDER C Pad

Location ID: 336021




Photo # 8626 Location



Photo # 8627 Location



**Inspection Photos**  
**Location Name: TEP ROCKY MOUNTAIN LLC SNYDER C Pad**  
**Location ID: 336021**



**Photo # 8628 Location**



**Photo # 8629 Cellar lacks wildlife egress**



**Inspection Photos**  
**Location Name: TEP ROCKY MOUNTAIN LLC SNYDER C Pad**  
**Location ID: 336021**



**Photo # 8630 PRV vent line terminates in an unsafe manner**



**Photo # 8631 Open ended load line**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SNYDER C Pad

Location ID: 336021



Photo # 8632 Open ended load line



Photo # 8633 Tank label damaged & becoming illegible

