

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/11/2024

Submitted Date:

03/11/2024

Document Number:

707800787

FIELD INSPECTION FORMLoc ID _____ Inspector Name: _____ On-Site Inspection ☐
Ramsey, Scott 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	
Arauza, Steven		steven.arauza@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
486172	SPILL OR RELEASE	AC	03/04/2024		-	Railsback Water Facility Release	AC

General Comment:**ECMC Inspection Report Summary**

On Thursday 3/7/2024, I, Inspector Scott Ramsey, conducted a storm water inspection at Caerus Rails back Water Facility, at Location # 335085 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed Oil absorbent booms placed in the ditch that runs from location to the north along roadway. There was also at the end of where the spill was terminated. An earth berm to contain any possible storm water, until they could get the contaminated soils removed. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. The location is approximately 1.5 miles from the 411 water protection area and 1000 feet from Mamm Creek. The release was found (broken flow line) outside of containment by hydovac truck.

A form 19n has been submitted document # 403705986.

This is a summary of inspection report.

Inspected Facilities									
Facility ID:	486172	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	AC

--

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Culverts						
Ditches						
Berms						
Waddles						Oil absorbent booms

Comment: This location is under active excavation of contaminated soils. Periodic random inspections will be performed throughout excavation process in order to observe maintance of BMP's.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707800788	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6461356