

# Interim Reclamation and Stormwater Inspection

Date: 03/11/2024

Operator: BONANZA CREEK ENERGY OPERATING  
COMPANY LLC - 8960

Location ID: 441915

Inspection Document #: 708200986

Weld County, CO

Dylan Edwardson  
Reclamation Specialist, ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: North Platte T-27 Pad  
Location ID: 441915



**Photos 1 & 2.** Western interim areas are not progressing towards Rule 1003 standards and regulations with evidence of undesirable vegetation (russian thistle and kochia) and areas of non-uniform vegetation cover resulting in exposed soils. Additional reclamation activities are required in order to comply with Rule 1003.



Inspection Photos  
Location Name: North Platte T-27 Pad  
Location ID: 441915



**Photos 3 & 4.** Southern interim areas; see comments in Photos 1 & 2.



Inspection Photos  
Location Name: North Platte T-27 Pad  
Location ID: 441915



**Photos 5 & 6.** Eastern interim ares; see comments in Photos 1 & 2.



Inspection Photos  
Location Name: North Platte T-27 Pad  
Location ID: 441915



**Photos 7 & 8.** Debris observed on location. Operator shall self inspect the location and ensure all debris/trash has been removed.



Inspection Photos  
Location Name: North Platte T-27 Pad  
Location ID: 441915



**Photo 9.** Debris on location. Operator shall self inspect the location and ensure all debris/trash has been removed.



Inspection Photos  
Location Name: North Platte T-27 Pad  
Location ID: 441915



**Photo 10.** Audible leak and apparent frost accumulation on valve at Well API 123-41883.