



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	good, Very Faded/Rusty		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	OTHER		
Comment:	electric disconnect panel, wire and post		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	safety guards		
Corrective Action:		Date:	

**Equipment:**

Type	Quantity	Comment	Corrective Action	Date	corrective date
Ancillary equipment	# 2	electrical disconnect panels			
Prime Mover	# 1	electric motor			
Bradenhead	# 1	piped to surface			
Pump Jack	# 1				

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 241194 Type: WELL API Number: 123-08982 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: FLOWLINE AVAILABLE-CONNECTED

Comment: Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well. Valves appeared to be closed at time of inspection

Corrective Action: Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.

Date: 04/12/2024

**BradenHead**

Date of Last Brhd Test: 09/05/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><u>ECMC Inspection Report Summary</u>  <u>Inspector Michael Kester,</u>  <u>conducted an on-site inspection.</u>  <u>Location: UPRR 43 Pan Am G 12</u>  <u>Operator: KPK</u>  <u>API#: 123-08982</u>  <u>County: Weld</u>  <u>While there, I observed well site with pumping unit,</u>  <u>During this inspection, the following possible compliance issues were observed:</u>  <u>Mechanical integrity Testing, Rule 417b, corrective action date 4-12-2024</u></p> <p><u>Weather conditions: over cast and dry</u>  <u>A follow up on this site inspection needs to be conducted to ensure the</u>  <u>Compliance issues have been corrected to comply with ECMC rules.</u>  <u>This is a summary of inspection report.</u></p> <p><u>This inspection does not nullify any orders or NOAV from the ECMC</u>  <u>This is a continuing education inspection</u></p>	kesterm	03/12/2024

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713300682	site pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6464276">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6464276</a>