

Inspection Photos
Location Name: Jillson A 1
Location ID: 333156



Energy & Carbon Management Commission
40°78', -105°021', 4874.8ft, 153°
03/13/2024 12:04:32



Energy & Carbon Management Commission
40°77', -105°021', 4872.8ft, 97°
03/13/2024 12:05:08

Photo 1 Location.

Photo 2 WH information faded.

Inspection Photos
Location Name: Jillson A 1
Location ID: 333156



Photo 3 WH is SI.

Photo 4 Wellsite, PJ disconnected from Rod, 5 monitor wells
3 are marked in photo.

Inspection Photos
Location Name: Jillson A 1
Location ID: 333156



Photo 5 Electric panel for the electric motor is shut off .



Photo 6 Monitor Well equipment.

Inspection Photos
Location Name: Jillson A 1
Location ID: 333156



Photo 7 Ancillary equipment is shut off and no meter on the meter box.