

Inspection Photos
Location Name: Wingo C.E. 2
Location ID: 323256

Mar 12, 2024 at 1:46:02 PM
40.071875,-104.949561
Weld County
ECMC



Pic 1 wellhead sign

Mar 12, 2024 at 1:45:44 PM
40.071875,-104.949561
Weld County
ECMC



Pic 2 pump jack, stained soil

Inspection Photos
Location Name: Wingo C.E. 2
Location ID: 323256



Pic 3 Stained soil / mechanical issue by wellhead. Stained soil needs to be removed.

Pic 4 Stained soil / mechanical issue by gas motor

Inspection Photos
Location Name: Wingo C.E. 2
Location ID: 323256



Pic 5 stained soil / mechanical issue