

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/08/2024

Submitted Date:

03/14/2024

Document Number:

705000645

FIELD INSPECTION FORMLoc ID 327907 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		ECMCInspections@Oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
247505	WELL	SI	09/01/2020	GW	123-15302	ASBURY GAS UNIT 1	PA
327907	LOCATION	AC			-	ASBURY GAS UNIT-62N67W 3SWNW	EG

General Comment:ECMC Engineering Integrity Inspection; Flowline Inspection
Photos uploaded

Inspected FacilitiesFacility ID: 247505 Type: WELL API Number: 123-15302 Status: SI Insp. Status: PA**Flowline**

#1	Type: Well Site	of Lines
----	-----------------	----------

Flowline Description

Flowline Type: Well Site Size: 2" Material: Carbon Steel
Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: Well is plugged and abandoned (Asbury GU 1); ECMC form 42 notice of start of plugging operations doc #403611391 received on 11/30/2023. The facility/ tank battery has been decommissioned; tanks and equipment removed. On location dump and process flowlines at facility/ battery are removed; ECMC form 42 notice of flowline abandonment completed doc #403703920 received 02/29/2024. No flowlines/ risers observed. Fenced excavations observed at PA well and facility/ battery areas. Excavation/ remediation work is in progress.

Corrective Action:

Date:

Facility ID: 327907 Type: LOCATION API Number: - Status: AC Insp. Status: EG**COGCC Comments**

Comment	User	Date
As outlined on COGCC form 19 spill report Doc #403703175 received on 03/01/2024: On February 28, 2024, historically impacted soil was discovered following facility decommissioning activities at the Asbury Gas UT1/Kniff Facility location. Excavation and assessment activities are ongoing. Site infrastructure has been removed and will not be replaced.	maclarej	03/14/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000648	Fenced excavation at PA well; signage	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6467046
705000649	Fenced excavations at facility/ battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6467047