

Inspection Photos
Location: Foster 14-2
API: 05-123-14822




Photo 1 –View looking northeast at former facility



Photo 2 – Unused equipment remaining on site

Inspection Photos
Location: Foster 14-2
API: 05-123-14822



Photo 3 – Unused disconnected equipment on site




Photo 4 – Undesirable vegetation