

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE EF03B19 D19A 595 Pad

Location # 335905



Mar 14, 2024 at 12:10:33 PM



Mar 14, 2024 at 12:20:07 PM

Photo # 80 From entrance to location

Photo # 81 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE EF03B19 D19A 595 Pad

Location # 335905



Photo # 82 Location



Photo # 83 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE EF03B19 D19A 595 Pad

Location # 335905



Mar 14, 2024 at 12:12:01 PM

Photo # 84 Location



Mar 14, 2024 at 12:22:54 PM

Photo # 85 Mechanical Condition - Casing valve on EF03B-19 well leaking fluid & gas

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE EF03B19 D19A 595 Pad

Location # 335905



Photo # 86 Wellhead signs lack required info



Photo # 87 Wellhead signs lack required info

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE EF03B19 D19A 595 Pad

Location # 335905



Photo # 88 Wellhead signs lack required info



Photo # 89 Wellhead signs lack required info