

Final Reclamation Inspection

March 12th, 2024

Operator: Simcoe LLC - 10749

Location ID: 307017

Inspection Document #: 714000538

La Plata County, CO

Township: NENE 21 33N 10W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Southern Ute 33-10; 21-1 2
Location ID: 307017



3/12/24
+37.096193,-107.933677
56° NE



Photo 1. Overview of the disturbance taken from the entrance facing center.

Inspection Photos

Location Name: Southern Ute 33-10; 21-1 2

Location ID: 307017



Photo 2. Trash/debris observed on location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-09562

Inspection Photos

Location Name: Southern Ute 33-10; 21-1 2

Location ID: 307017



Photo 3. Unused oil and gas equipment observed on location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-09562

Inspection Photos

Location Name: Southern Ute 33-10; 21-1 2

Location ID: 307017



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. View of eastern interim reclamation area facing north. Vegetation comprised of smooth brome and rabbitbrush.

API #: 067-09562

Inspection Photos

Location Name: Southern Ute 33-10; 21-1 2

Location ID: 307017



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Impacted material at well head corrective action identified in the previous inspection doc #712700262 has been addressed/resolved.

API #: 067-09562

Inspection Photos

Location Name: Southern Ute 33-10; 21-1 2

Location ID: 307017

3/12/24

+37.096668,-107.933769

264° W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 6. Reference area comprised of Smooth brome, Rabbit brush and sage brush.

API #: 067-09562