

Final Reclamation and Stormwater Inspection

March 4, 2024

Operator: Western Operating Company- #95620

Location ID: 319767

Inspection Document #: 709400855

Adams County, CO

SWSW Section 24 T3S R59W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Downing, Ralph 24-2
Location ID: 319767




Photo 1. Photo taken facing northeast of perimeter fence of reclamation area. The reclaimed area has been mowed, Russian thistle debris was observed in the fence. Weed debris indicated by yellow arrow.



Photo 2. Photo taken facing west of perimeter fence of reclamation area. The reclaimed area has been mowed, Russian thistle debris was observed in the fence. Weed debris indicated by yellow arrow.

Inspection Photos
Location Name: Downing, Ralph 24-2
Location ID: 319767



Photo 3. Photo taken facing west of perimeter fence of reclamation area. The reclaimed area has been mowed, Russian thistle debris was observed in the fence. Weed debris indicated by yellow arrow. Perennial vegetation is not apparent.



Photo 4. Photo taken facing east of perimeter fence of reclamation area. The reclaimed area has been mowed, Russian thistle debris was observed in the fence. Weed debris indicated by yellow arrow. Perennial vegetation is not apparent.

Inspection Photos
Location Name: Downing, Ralph 24-2
Location ID: 319767



Photo 5. Photo taken facing northwest of mowed vegetation in reclamation area. Perennial vegetation is not apparent.



Photo 6. Photo taken facing west of mowed vegetation and bare soil in reclamation area. Red arrow indicates bare soil.

Inspection Photos

Location Name: Downing, Ralph 24-2

Location ID: 319767



Photo 7. Photo taken facing southwest of mowed vegetation and bare soil in reclamation area. Red arrow indicates bare soil.

Photo 8. Photo taken facing north of mowed vegetation and bare soil in reclamation area. Red arrow indicates bare soil.



Inspection Photos

Location Name: Downing, Ralph 24-2

Location ID: 319767



Photo 9. Photo taken facing northwest of mowed vegetation in reclamation area. Perennial vegetation is not apparent.

Photo 10. Photo taken facing north of mowed vegetation and eroding bare soil in reclamation area. Red arrow indicates bare soil.



Inspection Photos

Location Name: Downing, Ralph 24-2

Location ID: 319767




Photo 11. Photo taken facing south of mowed vegetation and eroding bare soil in reclamation area. Red arrow indicates bare soil.




Photo 12. Photo taken facing north of mowed vegetation and eroding bare soil in reclamation area. Red arrow indicates bare soil.





Photo 13. Photo taken facing southwest of native vegetation for reference.

Inspection Photos

Location Name: Downing, Ralph 24-2

Location ID: 319767



Photo 14. Photo taken facing south of rutted access road.

Photo 15. Photo taken facing northwest of rutted access road.

