

**Operator: CRESTONE PEAK RESOURCES OPERATING LLC**

**Location Name: ALAUX F UNIT-61N68W 26NWNW**

**Loc ID: 321533**

**Inspection: 714300046**



**Exhibit A**

**CA:** No fencing is present around the location. Excavation is surrounded by soil berms which are inadequate for securing the excavation. Secure access to excavation in compliance with Rule 913.b.(5).B.i and ECMC Guidance 913.b.(5)B i-v

**CA Resolution:** Operator has appropriately installed fencing around the excavation to comply with Rule 913.b.(5).B.i.