

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MCLAUGHLIN 42A-27 Pad

Location ID: 335082



Photo # 9614 From entrance to location

Photo # 9615 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MCLAUGHLIN 42A-27 Pad

Location ID: 335082



Mar 13, 2024 at 10:13:10 AM
CO



Mar 13, 2024 at 10:14:41 AM
CO

Photo # 9616 Location

Photo # 9617 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MCLAUGHLIN 42A-27 Pad

Location ID: 335082



Photo # 9618 Location



Photo # 9619 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MCLAUGHLIN 42A-27 Pad

Location ID: 335082



Photo # 9620 Location



Photo # 9621 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MCLAUGHLIN 42A-27 Pad

Location ID: 335082



Photo # 9622 Unused equipment



Photo # 9623 Unused equipment/ECD disconnected & not in use

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MCLAUGHLIN 42A-27 Pad

Location ID: 335082



Photo # 9624 PRV vent line on tank burner terminates in an unsafe manner/does not comply with CECMC pressure safety device rules & general safety rules.



Photo # 9625 PRV vent line on tank burner terminates in an unsafe manner/does not comply with CECMC pressure safety device rules & general safety rules.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MCLAUGHLIN 42A-27 Pad

Location ID: 335082



Photo # 9626 PRV vent line on tank burner terminates in an unsafe manner/does not comply with CECMC pressure safety device rules & general safety rules.



Photo # 9627 42A-27 wellhead sign faded & illegible

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MCLAUGHLIN 42A-27 Pad

Location ID: 335082



Photo # 9628 Debris



Photo # 9629 Debris