

Inspection Photos

API: 099-06045

Operator: RENEGADE OIL & GAS COMPANY LLC

Inspection Date: 3/15/2024

County: Prowers



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast toward the tank battery. There is a new tank being installed which will need to follow the 603.k.o. requirements. Previous corrective action was not completed.



Inspection Photos



Photo 2. There is impacted oily material stored on a liner at the west side of the location. This is not properly stored to prevent stormwater from transporting the contaminated soil off the liner.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 099-06045 | Date: 3/15/2024

Inspection Photos



Photo 3. Facing northeast toward the tank battery where leak was previously observed. It appears the impacted material was partially scrapped away however there is still dark oily soil still evident around the tanks that extends out shown by red arrow.



Inspection Photos



Photo 4. Closer view at the tanks. It appear the produce water tank has a dripping leak. The oily soils around the crude oil tank have not been properly cleaned up.



Inspection Photos



Photo 5. Facing west toward the tank battery which had been significantly remodified and requires secondary containment per Rule 603.o. There is also no labeling of the crude oil tank at the right side of the photo. The produced water tank is labeled at the left tank.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 099-06045 | Date: 3/15/2024

Inspection Photos



Photo 6. Facing west toward the tank battery where leak was previously observed. It appears the impacted material was partially scrapped away however there is still dark oily soil still evident around the tanks. Tanks will need to be removed for proper clean up.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 099-06045 | Date: 3/15/2024

Inspection Photos



Photo 7. Facing north toward the wellhead. There is oil that has leak and sprayed out of the wellhead that needs to be cleaned up. Previous corrective action has not been completed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API: 099-06045 | Date: 3/15/2024

Inspection Photos



Photo 8. Facing west toward the wellhead. There is oil that has leak and sprayed out of the wellhead that needs to be cleaned up. Previous corrective action has not been completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 099-06045 | Date: 3/15/2024

Inspection Photos



Photo 9. Facing west at the south side of the location. Red arrow points to the unmarked guyline anchor. Unused areas of the location are not reclaimed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API: 099-06045 | Date: 3/15/2024

Inspection Photos



Photo 10. Facing southwest at the location. Unused areas of the location are not reclaimed. Fence is only up on the sides and does not prevent livestock entry.



Inspection Photos



Photo 4. Aerial view of the location shows unused areas of the location below and to the right of red line could be put back into cropland.

