

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/18/2024

Submitted Date:

03/18/2024

Document Number:

696306107

FIELD INSPECTION FORMLoc ID 434893 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10651

Name of Operator: VERDAD RESOURCES LLC

Address: 1125 17TH STREET SUITE 550

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

17 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Regulatory@verdadoil.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434893	LOCATION	AC			-	Castor 4-36-9-59 PAD	AC
434899	WELL	PR	08/01/2023	OW	123-38368	Castor 4-36-9-59	PR
434900	WELL	SI	08/01/2023	OW	123-38369	CASTOR 5-36-9-59	SI
435309	WELL	SI	08/01/2023	OW	123-38577	Castor 7-36-9-59	SI

General Comment:[This is a Well and Tank Battery Inspection](#)

LocationOverall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Various Tanks - NFPA, Content and Capacity Labels. See photos		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	04/19/2024
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	Belt Debris at Middle Pumping Unit; see photos		
Corrective Action:	Comply with Rule 606	Date:	04/01/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	

Equipment:

Type: Prime Mover	# 3		corrective date
Comment:	Electrical Motors		
Corrective Action:		Date:	

Type: Pump Jack	# 3		
Comment:			
Corrective Action:			Date:
Type: Flare	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 4		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 3		
Comment:	Appear to be plumbed to surface		
Corrective Action:			Date:
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:			Date:
Type: Vertical Heater Treater	# 3		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 4		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	3	400 BBLs	FIBERGLASS AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares berm with the Crude Oil Tanks				
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	9	400 BBLs	STEEL AST		40.713800,-103.918240
Comment:					
Corrective Action:					

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	Field Flare	
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 434893Type: LOCATIONAPI Number: -Status: ACInsp. Status: AC

Producing Well

Comment:Active Producing Production Facility

Corrective Action:

Date:

Facility ID: 434899Type: WELLAPI Number: 123-38368Status: PRInsp. Status: PR

Producing Well

Comment:PR

Corrective Action:

Date:

Facility ID: 434900Type: WELLAPI Number: 123-38369Status: SIInsp. Status: SI

Idle Well

Purpose:☒ Shut In☐ Temporarily AbandonedReminder:

Comment:SI

Corrective Action:

Date:

Facility ID: 435309Type: WELLAPI Number: 123-38577Status: SIInsp. Status: SI

Idle Well

Purpose:☒ Shut In☐ Temporarily AbandonedReminder:

Comment:SI

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
Routine Field Inspection. Tank Labels. Belt Debris at middle Pumping Unit	petrie	03/18/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696306108	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6471423

Date Run: 3/18/2024 Doc [#696306107]

Page 5 of 5