

Final Reclamation and Stormwater Inspection

March 4, 2024

Operator: Western Operating Company- #95620

Location ID: 319759

Inspection Document #: 709400857

Adams County, CO

NWSW Section 24 T3S R59W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**


Department of Natural Resources

Inspection Photos
Location Name: Downing, Ralph 24-1
Location ID: 319759



Mar 4, 2024 at 10:38:22 AM
Deer Trail CO 80105
United States

Photo 1. Photo taken facing northwest of excavation of removed well head and location.



Mar 4, 2024 at 10:38:33 AM
Deer Trail CO 80105
United States

Photo 2. Photo taken facing west of reclamation area vegetation and weeds(Russian thistle). Weeds indicated by yellow arrow.

Inspection Photos
Location Name: Downing, Ralph 24-1
Location ID: 319759



Photo 3. Photo taken facing northeast of reclamation area, weeds (russian thistle) and access road. Weeds indicated by yellow arrow.



Photo 4. Photo taken facing west of excavation of anchor removed onsite. , Red arrow indicates excavation.

Inspection Photos
Location Name: Downing, Ralph 24-1
Location ID: 319759



Photo 5. Photo taken facing southeast of removed anchors.



Photo 6. Photo taken facing southwest of vegetation and cut slope that has not been recontoured in reclamation area. Yellow arrow indicates cut slope.

Inspection Photos

Location Name: Downing, Ralph 24-1

Location ID: 319759



Photo 7. Photo taken facing north of removed well head and excavation on site.



Photo 8. Photo taken facing north of removed well head excavation on site.

Inspection Photos

Location Name: Downing, Ralph 24-1

Location ID: 319759




Photo 9. Photo taken facing southwest of excavation of anchor on southwest side of site in reclamation area.

Photo 10. Photo taken vegetation and weeds (russian thistle) soil in reclamation area. Weeds indicated by yellow arrow.

Inspection Photos

Location Name: Downing, Ralph 24-1

Location ID: 319759



Photo 11. Photo taken facing south of bull thistle in reclamation area.



Photo 12. Photo taken facing south of bull thistle in reclamation area.



Photo 13. Photo taken facing southwest of native vegetation for reference.

Inspection Photos

Location Name: Downing, Ralph 24-1

Location ID: 319759



Photo 14. Photo taken facing south of rutted access road.

Photo 15. Photo taken facing northwest of rutted access road.

