

Inspection Photos

Location Name: ROUSE USX AB-67N64W/33SWSW

Location #: 302629



Photo #1

Rouse USX AB 33-13 (123-29500) Wellsite

Plugged & Abandoned | PA

Plugging Ops; Cementing: cmt-surf



Photo #2

Rouse USX AB 33-13 Wellsite

Plugged & Abandoned | PA

Plugging Ops; Cementing: cmt-surf

Site safety signage



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos
Location Name: ROUSE USX AB-67N64W/33SWSW
Location #: 302629



Colorado Energy & Carbon Management Commission
 Weld County
 40.522606 -104.556857
 354° N
 2024-03-18 12:00

Photo #3
Rouse USX AB 33-13 Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: cmt-surf
Wellsite entrance




Photo #4
Rouse USX AB 33-13 Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: cmt-surf
JSA: 2024-03-12



Colorado Energy & Carbon Management Commission
 Weld County
 40.522606 -104.556857
 277° W
 2024-03-18 11:45

Inspection Photos

Location Name: ROUSE USX AB-67N64W/33SWSW

Location #: 302629



Photo #5

Rouse USX AB 33-13 Battery site

Plugged & Abandoned | PA

Plugging Ops; Cementing: cmt-surf

Battery sign



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources