

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/18/2024

Submitted Date:

03/18/2024

Document Number:

707602503

FIELD INSPECTION FORM

Loc ID: 302629 Inspector Name: Evins, Bret On-Site Inspection: 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 2001 16TH STREET SUITE 900
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
299737	WELL	SI	09/01/2020	OW	123-29500	ROUSE USX AB 33-13	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL / WORKOVER / CEMENTING** inspection.
Well(s): 1: Plugged & Abandoned | PA.
Plugging Operations: Cementing; Cement-surface.
Battery: Inactive. Shut-down.
Inactive Battery SE corner GPS coordinates: 40.522864 / -104.564086
Well GPS coordinates: 40.523780 / -104.562560

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Jobsite entrance & safety signage posted.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Plunger Lift	# 0		corrective date
Comment:	Plugged & Abandoned PA. Equipment removed.		
Corrective Action:			Date:
Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 299737 Type: WELL API Number: 123-29500 Status: SI Insp. Status: PA

Cement

Cement Contractor

Contractor Name: Axis Energy Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____ Circulate to Surface: _____
 Cement Fall Back: _____ Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____ Cement Volume (sx): 295 sxs

Good Return During Job: _____ Cement Type: Class "G" Neat 15.8#

Comment: 2024/03/18:
 Plugging Operations: Cementing; cement-surface.
 2024/03/18: JSA attached as photo to this report.

Workover Contractor: Axis Energy Services Rig #714.
 Cement Contractor: Axis Energy Services.

Reference:
 Form 6N on file. Notice of Intent to Abandon date: 02/16/2024. Approved.
 Form 42 on file. Notice of MIRU. Start Date: 03/11/2024. Approved.
 Form 42 on file. Notice of Plugging Operations. Start Date: 03/11/2024. Approved.

CTL, HSM AND REVIEW SIF HAZARDS & MITIGATION ON WORKING @ HIGHTS-FILL OUT SWC. CHECK IWP=0 SICP/ 0 SIBHP-OPEN WELL RIH W/ SN/NC AND 82 JTS 2-3/8" TBG AND 26' SUB TO 2561'. HSM W/ AXIS CMT-MIRU CMT CREW. PRESSURE TEST LINES TO 1500 PSI-ESTABLISH CIRC, MIX AND PUMP 10 SKS 15.8 PPG G NEAT CMT 2 BBLS SLURRY. DISPLACE W/ 9.4 BBLS TO BALANCE EST TOC @ 2432'. RDMO CMT CREW-POOH LD 26' SUB AND 82 JTS 2-3/8" TBG SN/NC. PERFORM 15 MIN INFLOW TEST (WSEA 10-A)=NO FLOW. RD WORK FLOOR-ND BOP/NU WH. ESTABLISH CIRCULATION AND CONDITION HOLE W/1 BOTTOM UP THROUGH SZQ HOLE @ 822'. HSM W/ AXIS CMT-RETEST LINES TO 1500 PSI ESTABLISH CIRC W/ 2 BBLS. PUMP 10 BBLS MUD FLUSH 5 BBLS FW SPACER MIX AND PUMP 285 SKS 15.8 PPG G NEAT CMT TO SRF 58 BBL SLURRY. WAIT 15 MIN TOP OF W/ .5 BBL. RDMO CMT CREW. SI AND SECURE WELL. CLEAN WORK TANKS. RD RIG AND EQUIPMENT.

Corrective Action: _____ Date: _____

Workover

Comment: 2024/03/18:
 Plugging Operations: Cementing; cement-surface.
 2024/03/18: JSA attached as photo to this report.

Workover Contractor: Axis Energy Services Rig #714.
 Cement Contractor: Axis Energy Services.

Reference:
 Form 6N on file. Notice of Intent to Abandon date: 02/16/2024. Approved.
 Form 42 on file. Notice of MIRU. Start Date: 03/11/2024. Approved.
 Form 42 on file. Notice of Plugging Operations. Start Date: 03/11/2024. Approved.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass			Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On MON 03/18/2024 at approximately 11:47 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: ROUSE USX AB-67N64W/33SWSW Location ID: 302629 Well Name(s): Rouse USX AB 33-13. API: 123-29500. Location County: Weld County, Colorado Weather: Mostly Sunny, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Plugging Operations: Cementing; Cement-surface. Battery: Inactive. Shut-down. Inactive Battery SE corner GPS coordinates: 40.522864 / -104.564086 Well GPS coordinates: 40.523780 / -104.562560</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	03/18/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602504	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6472176