

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/18/2024

Submitted Date:

03/18/2024

Document Number:

713300706

**FIELD INSPECTION FORM**Loc ID 318675 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

10 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name  | Phone        | Email                    | Comment         |
|---------------|--------------|--------------------------|-----------------|
| , KPK         | 303-825-4822 | cogcc@kpk.com            | all inspections |
| Silver, Randy | 720-827-6688 | randy.silver@state.co.us |                 |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name           | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------------|-------------|
| 241880      | WELL | SI     | 05/01/2021  | GW         | 123-09671 | JOSEPH L HUETT UNIT C 1 | SI          |

**General Comment:**

**Location**Overall Good: ☒

|                      |   |       |  |
|----------------------|---|-------|--|
| <b>Signs/Marker:</b> |   |       |  |
| Type                 | WELLHEAD                                  |       |  |
| Comment:             | not fastened, on ground next to well head |       |  |
| Corrective Action:   |   | Date: |  |

|                           |  |  |             |
|---------------------------|--|--|-------------|
| Emergency Contact Number: |  |  |             |
| Comment:                  |  |  |             |
| Corrective Action:        |  |  | Date: _____ |

|                           |                           |       |            |
|---------------------------|---------------------------|-------|------------|
| <b>Good Housekeeping:</b> |                           |       |            |
| Type                      | DEBRIS                    |       |            |
| Comment:                  | DEAD overgrown vegetation |       |            |
| Corrective Action:        | Comply with Rule 606      | Date: | 04/18/2024 |

Overall Good: ☐

|                |      |        |  |  |  |
|----------------|------|--------|--|--|--|
| <b>Spills:</b> |      |        |  |  |  |
| Type           | Area | Volume |  |  |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |               |       |  |
|--------------------|---------------|-------|--|
| <b>Fencing/:</b>   |               |       |  |
| Type               | WELLHEAD      |       |  |
| Comment:           | post and wire |       |  |
| Corrective Action: |               | Date: |  |
| Type               | PUMP JACK     |       |  |
| Comment:           | safety guards |       |  |
| Corrective Action: |               | Date: |  |

|                           |                                  |       |                 |
|---------------------------|----------------------------------|-------|-----------------|
| <b>Equipment:</b>         |                                  |       | corrective date |
| Type: Pump Jack           | # 1                              |       |                 |
| Comment:                  |                                  |       |                 |
| Corrective Action:        |                                  | Date: |                 |
| Type: Bradenhead          | # 1                              |       |                 |
| Comment:                  | piped to surface                 |       |                 |
| Corrective Action:        |                                  | Date: |                 |
| Type: Prime Mover         | # 1                              |       |                 |
| Comment:                  | natural gas                      |       |                 |
| Corrective Action:        |                                  | Date: |                 |
| Type: Ancillary equipment | # 3                              |       |                 |
| Comment:                  | electrical and automation panels |       |                 |
| Corrective Action:        |                                  | Date: |                 |



**Inspected Facilities**Facility ID: 241880 Type: WELL API Number: 123-09671 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: FLOWLINE AVAILABLE-CONNECTED

Comment: Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well. Valves appeared to be closed at time of inspection

Corrective Action: Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.

Date: 04/18/2024**BradenHead**Date of Last Brhd Test: 08/17/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**COGCC Comments**

| Comment   | User    | Date       |
|---|---------|------------|
| <p>ECMC Inspection Report Summary<br/>Inspector Michael Kester,<br/>conducted an on-site inspection.<br/>Location: Joseph L Huett UT C1<br/>Operator: KPK<br/>API#: 123-09671<br/>County: Weld<br/>While there, I observed well site with pumping unit,<br/>During this inspection, the following possible compliance issues were observed:<br/>Mechanical integrity Testing, Rule 417b, corrective action date 4-18-2024<br/>Debris, Dead vegetation, Rule 606, corrective action date 4-18-20224, all photos</p> <p>Weather conditions: sunny and dry<br/>A follow up on this site inspection needs to be conducted to ensure the<br/>Compliance issues have been corrected to comply with ECMC rules.<br/>This is a summary of inspection report.</p> <p>This inspection does not nullify any orders or NOAV from the ECMC<br/>This is a continuing education inspection</p> | kesterm | 03/18/2024 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 713300707    | site pic    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6472317">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6472317</a> |