

Inspection Photos

API: 099-06872

Operator: STRACHAN EXPLORATION INC

Inspection Date: 3/15/2024

County: Prowers



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast toward the wellsite location.



Inspection Photos



Photo 2. Facing southwest at the wellsite. There was no sign posted at the wellsite.



Inspection Photos



Photo 3. Facing toward the fiberglass tank. The fence around the tank is not maintained to prevent livestock entry.



Inspection Photos



Photo 4. Facing toward the well. There is unused equipment and drilling pipe that needs to be removed..



Inspection Photos



Photo 5. The fence around the pumpjack is insufficient to prevent livestock entry.



Inspection Photos



Photo 6. There were 4 dead birds pulled out of the tank.

