

Inspection Photos

API: 099-06328

Operator: BERRY* WALTER V DBA BERRY ENERGY INC

Inspection Date: 3/15/2024

County: Prowers



Inspection Photos



Photo 1. Facing east toward the location. This area has not established a perennial uniform cover and consists mostly of undesirable weeds.



Inspection Photos



Photo 2. There is an abandoned pipe riser that remains on location that was never removed..



Inspection Photos



Photo 3. Facing west at the location. This area (approx. 200'x60') has not established a perennial uniform cover and consists mostly of undesirable weeds.



Inspection Photos



Photo 4. Facing north at the location. This area (approx. 100'x40') has not established a perennial uniform cover and consists mostly of undesirable weeds.



Inspection Photos



Photo 5. Facing east at the undisturbed surrounding reference area shows a uniform native Blue grama prairie with no weeds.

