

Inspection Photos

ID: 444661

Operator: STRACHAN EXPLORATION INC

Inspection Date: 3/15/2024

County: Prowers



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast toward the compressor facility.



Inspection Photos



Photo 2. Facing northeast toward the tank. There is a leak that occurred at the tank within the secondary containment. There is insufficient labeling and signage at the tank .



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

ID: 444661 | Date: 3/15/2024

Inspection Photos



Photo 3. Facing east toward the tank. There is a leak that occurred at the tank within the secondary containment. There is insufficient labeling and signage at the tank .



Inspection Photos



Photo 4. Facing toward the tank. There is a leak that occurred at the tank within the secondary containment. There is insufficient labeling and signage at the tank .



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

ID: 444661 | Date: 3/15/2024

Inspection Photos



Photo 5. There is a bird nest at the top of the tank that should not be disturbed. Operator will need to contact CPW or USFS regarding bird nest.



Inspection Photos



Photo 6. There is a bird nest at the top of the tank that should not be disturbed. Operator will need to contact CPW or USFS regarding bird nest.

