

Inspection Photos and Issue Report

3/18/2024

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 486086

Inspection Doc: 696205680

Rio Blanco County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 486086



Photo 1: Photos 1-2 taken from the Location entrance on the southwest end of the site. Photos provide an overview of the Location from northwest, north, northeast to east. Photo shows grubbing activities have commence / been completed. Operator in process of installing erosion logs along the western perimeter of the Location; stormwater and erosion control BMPs remain missing along remaining disturbance perimeter.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 486086



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 486086



Photo 3: Photos 3-4 taken from the North end of the Location. Photos provide an overview of the Location from east, southeast, southwest to west. Photo shows grubbing activities have commence / been completed. Operator in process of installing erosion logs along the western perimeter of the Location; stormwater and erosion control BMPs remain missing along remaining disturbance perimeter.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 486086



Photo 4: See comments under photo 3.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 486086



Photo 5: Photos 5-6 taken from the Northeast end of the Location. Photos provide an overview of the Location from east, southeast, southwest to west. Photo shows grubbing activities have commence / been completed. Operator in process of installing erosion logs along the western perimeter of the Location; stormwater and erosion control BMPs remain missing along remaining disturbance perimeter.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 486086



Photo 6: See comments under photo 5.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 486086



Photo 7: Photos taken from the southeast end of the Location. Photos provide an overview of the Location from northwest to northeast. Photo shows grubbing activities have commence / been completed. Operator in process of installing erosion logs along the western perimeter of the Location; stormwater and erosion control BMPs remain missing along remaining disturbance perimeter.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 486086



Photo 8: Photos taken from the access road entrance and CR 68. Photo shows culvert installation along access road.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 486086



Photo 9: Photos show disturbance area of the access road.