


KT Resources LLC
 Ant Hill Unit 8-32
 Location ID: 316321



Calibration out of compliance

Erosion and sediment migration

**KT Resources LLC
Ant Hill Unit 8-32
Location ID: 316321**



Previous year weed debris



As signs are replaced additional information is required

**KT Resources LLC
Ant Hill Unit 8-32
Location ID: 316321**



Stained soil



Erosion and sediment migration

**KT Resources LLC
Ant Hill Unit 8-32
Location ID: 316321**



Location from Southwest corner



Location from Northwest corner

**KT Resources LLC
Ant Hill Unit 8-32
Location ID: 316321**



Location from Northeast corner



Location from Southeast corner