

Final Reclamation Inspection

March 12th, 2024

Operator: Enduring Resources LLC - 10663

Location ID: 326276

Inspection Document #: 714000571

La Plata County, CO

Township: SWSE 3 34N 9W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Crader 3-2
Location ID: 326276



Photo 1. Overview of the disturbance taken from the entrance facing center.

Inspection Photos
Location Name: Crader 3-2
Location ID: 326276




Photo 2. Weedy debris observed in the eastern interim reclamation fill slope and in the southern interim reclamation area at the access point. Fill slope lacks desirable vegetation and needs to be stabilized.

Inspection Photos
Location Name: Crader 3-2
Location ID: 326276



Photo 3. Unused cone observed on location.



Inspection Photos
Location Name: Crader 3-2
Location ID: 326276




Photo 4. Stormwater corrective action identified in the previous inspection doc #714000031 has been addressed/resolved.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-07759

Inspection Photos
Location Name: Crader 3-2
Location ID: 326276



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Reference area comprised of smooth brome, indian rice grass, gambel oak and juniper.

API #: 067-07759