

Inspection Photos
Location Name: Castor LC 26-75HN
Location ID: 422629



Photo 1 – Pumping Unit

Photo 2 – Wellhead Sign

Inspection Photos
Location Name: Castor LC 26-75HN
Location ID: 422629



Energy and Carbon Management Commission
40.71544, -103.94483, 4736.4ft
03/19/2024 11:59:14



Energy and Carbon Management Commission
40.71546, -103.94499, 4733.3ft
03/19/2024 11:59:31

Photo 3 – Oily Waste in Containment

Photo 4 – Gas Engine

Inspection Photos
Location Name: Castor LC 26-75HN
Location ID: 422629



Energy and Carbon Management Commission
40.71547, -103.94494, 4739.1ft
03/19/2024 11:59:54



Energy and Carbon Management Commission
40.71548, -103.94493, 4734.0ft
03/19/2024 12:00:00

Photo 5 – Oily Waste in Containment

Photo 6 – Stained Soil

Inspection Photos
Location Name: Castor LC 26-75HN
Location ID: 422629




Photo 7 – Wellhead




Photo 8 – Stained Soil at Wellhead

Inspection Photos
Location Name: Castor LC 26-75HN
Location ID: 422629



Photo 9 – Gas Meters and VRU

Photo 10 – Separators

Inspection Photos
Location Name: Castor LC 26-75HN
Location ID: 422629




Photo 11 – Tank Battery



Photo 12 – NFPA Labels

Inspection Photos
Location Name: Castor LC 26-75HN
Location ID: 422629



Energy and Carbon Management Commission
40.71505, -103.944, 4765.3ft
03/19/2024 12:03:06



Energy and Carbon Management Commission
40.71492, -103.94397, 4766.5ft
03/19/2024 12:03:16

Photo 13 – NFPA Labels

Photo 14 – Tank Battery Sign

Inspection Photos
Location Name: Castor LC 26-75HN
Location ID: 422629



Energy and Carbon Management Commission
40.71479, -103.94381, 4775.9ft
03/19/2024 12:03:39



Energy and Carbon Management Commission
40.71529, -103.94373, 4769.7ft
03/19/2024 12:03:58

Photo 15 – Tank Battery – Backside

Photo 16 – ECD