

Inspection Photos
Location Name: Douglas LC 35-785 PAD
Location ID: 440068



Energy and Carbon Management Commission
40.71548, -103.9512, 4756.7ft
03/19/2024 12:10:25



Energy and Carbon Management Commission
40.71549, -103.95172, 4752.0ft
03/19/2024 12:10:52

Photo 1 – Wellheads

Photo 2 – LC26-780 Wellhead – Sec. # not adequate Well is in Sec. 26 not Sec. 34

Inspection Photos
Location Name: Douglas LC 35-785 PAD
Location ID: 440068





Photo 3 – LC35-780 Wellhead – Sec. # not adequate Well is in Sec. 26 not Sec. 34

Photo 4 – LC35-770 Wellhead – Sec. # not adequate Well is in Sec. 26 not Sec. 34

Inspection Photos
Location Name: Lynn LC 35-765 PAD
Location ID: 440072



Photo 5 – LC26-770 Wellhead – Sec. # not adequate Well is in Sec. 26 not Sec. 34

Photo 6 – Gas Lift Injection Meter House