

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/20/2024

Submitted Date:

03/20/2024

Document Number:

696306115**FIELD INSPECTION FORM**Loc ID 440068 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1099 18TH STREET SUITE 1500City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
440055	WELL	PR	08/01/2020	OW	123-40659	JD LC26-780	PR
440056	WELL	PR	08/01/2020	OW	123-40660	DOUGLAS LC35-770	PR
440059	WELL	PR	08/01/2020	OW	123-40662	JD LC26-770	PR
440064	WELL	PR	08/01/2020	OW	123-40667	DOUGLAS LC35-780	PR

General Comment:

This is a Well PAD Inspection.

LocationOverall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	Legal Section # not adequate – Well PAD is in Section 26 not Section 34; see photos		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	04/22/2024
Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	

Equipment:

Type: Bradenhead	# 4		corrective date
Comment:	Appear to be plumbed to surface		
Corrective Action:		Date:	
Type: Pump Jack	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 4		
Comment:	Gas Lift Injection Meter House		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected FacilitiesFacility ID: 440055 Type: WELL API Number: 123-40659 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 440056 Type: WELL API Number: 123-40660 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 440059 Type: WELL API Number: 123-40662 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 440064 Type: WELL API Number: 123-40667 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment

User

Date

Routine Field Inspection. Legal Section # not adequate – Well PAD is in Section 26 not Section 34; see photos

petrie

03/20/2024

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696306116	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6475699