



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Pumping unit and equipment, disassembled		
Corrective Action:	Comply with Rule 606	Date:	04/22/2024

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	OTHER		
Comment:	electric/automation equipment, metal panels		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	safety guards and post/wire		
Corrective Action:		Date:	

**Equipment:**

Type			corrective date
Type: Bradenhead	# 1		
Comment:	pipied to surface		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	automation/electric panels		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 241089 Type: WELL API Number: 123-08877 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: FLOWLINE AVAILABLE-CONNECTED

Comment: Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well. Valves appeared to be closed at time of inspection

Corrective Action: Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.

Date: 04/22/2024

**BradenHead**

Date of Last Brhd Test: 09/07/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 3 Fluid Type: \_\_\_\_\_  
End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><u>ECMC Inspection Report Summary</u>  <u>Inspector Michael Kester,</u>  <u>conducted on-site inspection</u>  <u>Location: Suckla Brown UT 16</u>  <u>Operator: KPK</u>  <u>API#: 123-08877</u>  <u>County: Weld</u>  <u>While there, I observed well site with disassembled pumping unit,</u>  <u>During this inspection, the following possible compliance issues were observed:</u>  <u>Unused equipment, Rule 606, corrective action date 4-22-2024</u>  <u>Mechanical integrity Testing, Rule 417b, corrective action date 4-22-2024</u>  <u>Weather conditions: sunny and dry</u>  <u>A follow up on this site inspection needs to be conducted to ensure the</u>  <u>Compliance issues have been corrected to comply with ECMC rules.</u>  <u>This is a summary of inspection report.</u>  <u>This inspection does not nullify any orders or NOAV from the ECMC</u>  <u>This is a continuing education inspection</u></p>	kesterm	03/20/2024

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713300733	site pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6475704">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6475704</a>