

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SOUTH LEVERICH 18-13 Pad

Location ID: 335049



Mar 20, 2024 at 11:11:51 AM

Photo # 604 From entrance to location



Mar 20, 2024 at 11:11:55 AM

Photo # 605 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SOUTH LEVERICH 18-13 Pad

Location ID: 335049



Photo # 606 Location



Photo # 607 Location

Inspection Photos


Location Name: TEP ROCKY MOUNTAIN LLC SOUTH LEVERICH 18-13 Pad

Location ID: 335049



Mar 20, 2024 at 11:12:29 AM

Photo # 608 Location



Mar 20, 2024 at 11:17:15 AM

Photo # 609 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SOUTH LEVERICH 18-13 Pad

Location ID: 335049



Photo # 610 Location



Photo # 611 Mechanical condition/Fluid leaking onto the ground from S. Leverich 13-16C wellhead

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SOUTH LEVERICH 18-13 Pad

Location ID: 335049



Photo # 612 Stained soils & gravel around S. Leverich 13-16C wellhead



Photo # 613 Stored trailer/unused equipment

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SOUTH LEVERICH 18-13 Pad

Location ID: 335049



Photo # 614 Open ended load line



Photo # 615 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SOUTH LEVERICH 18-13 Pad

Location ID: 335049



Photo # 616 Debris