

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/21/2024

Submitted Date:

03/21/2024

Document Number:

697009124

FIELD INSPECTION FORMLoc ID 307208 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 52530

Name of Operator: MAGPIE OPERATING INC

Address: 2707 SOUTH COUNTY RD 11

City: LOVELAND State: CO Zip: 80537

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|-------|---------------------------------|---------|
| Donahue, Jessica | | jdonahue@ardonenvironmental.com | |
| Warner, Ross | | ross.magpieoil@gmail.com | |
| Fanning, Trisha | | tfanning@ardonenvironmental.com | |
| Kost, Jody | | magpieoil2@yahoo.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 217139 | WELL | SI | 11/01/2023 | GW | 069-06326 | WOOLDRIGE-COULSON 1 | WK |

General Comment:

This is a well plugging inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

LocationOverall Good: ☒

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | DRILLING/RECOMP | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|--------------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Pipe fencing | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------------|----------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Flow Line | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Vertical Separator | # 1 | | |
| Comment: | Anchored | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |

| | | | | |
|--------------------------|--|--|-------|--|
| Comment: | Bradenhead valve is exposed at surface | | Date: | |
| Corrective Action: | | | Date: | |
| Type: Deadman # & Marked | # 4 | | | |
| Comment: | | | Date: | |
| Corrective Action: | | | Date: | |
| Type: Plunger Lift | # 1 | | | |
| Comment: | | | Date: | |
| Corrective Action: | | | Date: | |
| Type: Other | # | | | |
| Comment: | Rig, pump and work tanks are grounded | | Date: | |
| Corrective Action: | | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|----------|----------|-----------|---------|--------|
| CRUDE OIL | 1 | 300 BBLs | STEEL AST | | , |
| Comment: | Anchored | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---------|-----------|-----------|---------|--------|
| PRODUCED WATER | 1 | <100 BBLs | PBV STEEL | | , |
| Comment: | 80 bbls | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Inspected FacilitiesFacility ID: 217139 Type: WELL API Number: 069-06326 Status: SI Insp. Status: WK**Cement**Cement ContractorContractor Name: Ranger Energy

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____

Cement Volume (sx): 50 sxsGood Return During Job: YESCement Type: Class G Neat 15.8#

Comment: Initial BH @ 28 psig with slight water flow, RU RMWS e-line, RIH and perforate csg @ 500' KB 6 SPF for annular squeeze, POOH with spent gun, RD e-line, MIRU Ranger Energy Services cementers, establish circulation, mix and pump 50 sxs Class G Neat 15.8 ppg cement slurry (10.2 bbls total) down production csg, displace csg with 6.7 bbls of fresh water, SIW, RDMO cementers.

Corrective Action: _____

Date: _____

BradenHeadDate of Last Brhd Test: 07/14/2023Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 55Fluid Type: WATER H2OEnd Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

| | | | | | | |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Gravel | Pass | Gravel | Pass | | | |

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| | | |
|--------------|-------------|---|
| Document Num | Description | URL |
| 697009125 | Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6476849 |