

Inspection Photos
Location Name: James a Damiana #1
Location ID: 336455



Photo 1 TNK BTRY



Photo 2 TNK BTRY sign rusted and not legible

Inspection Photos
Location Name: James a Damiana #1
Location ID: 336455



Photo 3 Debris in containment



Photo 4 risers not ooslat tagged. Meter no card and meter is non operational

Inspection Photos
Location Name: James Damiana #1
Location ID: 336455




Photo 5 writing on crude oil tank



Photo 6 Produced water vault NFPA Placard faded.

Inspection Photos
Location Name: James a Damiana #1
Location ID: 336455



Photo 7 Well head sign faded not legible



Photo 8 loc pic

Inspection Photos
Location Name: James Damiana #1
Location ID: 336455



Photo 9 piping has not OOSLAT tags



Photo 10 Mechanical issue and stained soil on ground of Hoz sep.