

Inspection Photos
Location Name: Coan 17-33#17-33
Location ID: 331435



Photo 1 Access road mowed not maintained



Photo2 Well head Dead vegetation around well head

Inspection Photos
Location Name: Coan 17-33#17-33
Location ID: 331435



Photo 3 Heater stack installed Dead vegetation around separator



Photo 4 Meter house not connected to sales flow line not operational

Inspection Photos
Location Name: Coan 17-33#17-33
Location ID: 331435



Photo 5 Dead vegetation around equipment



Photo 6 Battery sign not replaced no volume on produced water tank

Inspection Photos
Location Name: Coan 17-33#17-33
Location ID: 331435



Photo 7 Oil tank has no placards or volume signs



Photo 8 well head sign has not been replaced with correct well number

Inspection Photos
Location Name: Coan 17-33#17-33
Location ID: 331435



Photo 9 Wildlife protection hole in produced water tank



Photo 10 TNK BTRY sign does not reflect correct well number

Inspection Photos
Location Name: Coan 17-33#17-33
Location ID: 331435



Photo 11 access road mowed not maintained



Photo 12 Access road mowed not maintained

Inspection Photos
Location Name: Coan 17-33#17-33
Location ID: 331435



Photo 13 Access road mowed not maintained



Photo 14 Debris cut down in and around secondary containment but not removed

Inspection Photos
Location Name: Coan 17-33#17-33
Location ID: 331435



Photo 15 Dead vegetation in secondary containment



Photo 16 Dead vegetation in secondary containment