

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/21/2024

Submitted Date:

03/21/2024

Document Number:

707901449

FIELD INSPECTION FORM

Loc ID 331435 Inspector Name: Silver, Randy On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.
,	303-825-4822	cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262053	WELL	PR	02/01/2023	GW	123-20683	COAN 17-33 17-33	SI

General Comment:

[This is a follow up inspection per Doc#707901335](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment: Reporting No Firr was submitted to ECMC

Corrective Action: Comply with rule 210

Date:

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 262053 Type: WELL API Number: 123-20683 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: SI At time of inspectio flow line appear to be in the closed position.

Corrective Action: Date:

COGCC Comments

Comment	User	Date
This is a follow up inspection per doc# 707901335. At time of inspection it appears the only corrective address and completed was mechanical issue for the Hozontal seperator burner stack installed. At time of inspection all other corrective action had not been addressed. Road and facility had been mowed but as stated in previous inspection road and location had debris that needed to be removed from seconday containment and around equipment, and road need to be maintained per photos neither were completed fully. In addition Production reports and braden head reports that wre requested by inspector by 2-20-24 they were not recevied through the FIRR process. KPK will recieve a corrective action for non reporting of FIRR and do non compliance of corrective actions in previous inspection, inspection will be submitted for NOAV.	silverr	03/21/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707901450	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6477550