

Inspection Photos

Loc: 424805

Operator: **JAVERNICK OIL**

Inspection Date: 3/20/2024

County: FREMONT



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northwest at the beginning of the access road. There is undesirable weeds along the access and the access road has not been reclaimed..



Inspection Photos



Photo 2. Facing south toward the location which has not been reclaimed per 1004 Rules. The fence remains around the location and is not maintained.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:424805 | Date: 3/20/2024

Inspection Photos



Photo 4. Facing northwest at the location. There is tall dry undesirable weeds throughout the location which is a fire hazard.



Inspection Photos



Photo 5. Southeast corner of the location facing north along the fill slope. There are undesirable growing along the fill slope that need to be controlled. The location has not been recontoured. Previous corrective action was not completed.



Inspection Photos



Photo 6. Facing northwest along the cut slope. There is rilling erosion along the cut slope which is not stabilized. Previous corrective action was not completed.



Inspection Photos



Photo 6. There are two gravel pile at the remain at the northwest corner of the Location. Previous corrective action was not completed.



Inspection Photos



March 20, 2024
+38.376445, -105.117465

Photo 7. Facing southwest toward the cut slope.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:424805 | Date: 3/20/2024

Inspection Photos



Photo 8. Facing south at the location.

