

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/25/2024

Submitted Date:

03/25/2024

Document Number:

697009148

**FIELD INSPECTION FORM**

Loc ID 319108 Inspector Name: Peterson, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 47120  
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-

**Findings:**

9 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email                   | Comment |
|--------------|-------|-------------------------|---------|
|              |       | ECMCInspections@Oxy.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 242908      | WELL | TA     | 01/01/2024  | OW         | 123-10699 | CRESSWELL 1   | TA          |

**General Comment:**

This is a routine inspection. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator personnel on location at the time of this field inspection.

**Location**

Overall Good:

**Signs/Marker:**

|                    |                      |  |       |
|--------------------|----------------------|--|-------|
| Type               | BATTERY              |  |       |
| Comment:           |                      |  |       |
| Corrective Action: |                      |  | Date: |
| Type               | WELLHEAD             |  |       |
| Comment:           |                      |  |       |
| Corrective Action: |                      |  | Date: |
| Type               | TANK LABELS/PLACARDS |  |       |
| Comment:           |                      |  |       |
| Corrective Action: |                      |  | Date: |

Emergency Contact Number:

Comment:

Corrective Action:

  


Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

|                    |                   |  |       |
|--------------------|-------------------|--|-------|
| Type               | IGNITOR/COMBUSTOR |  |       |
| Comment:           | Panel             |  |       |
| Corrective Action: |                   |  | Date: |
| Type               | WELLHEAD          |  |       |
| Comment:           | Panel             |  |       |
| Corrective Action: |                   |  | Date: |

**Equipment:**

| Type                      |                                               |  | corrective date |
|---------------------------|-----------------------------------------------|--|-----------------|
| Type: Flow Line           | # 1                                           |  |                 |
| Comment:                  |                                               |  |                 |
| Corrective Action:        |                                               |  | Date:           |
| Type: Gas Meter Run       | # 1                                           |  |                 |
| Comment:                  | Western Midstream calibration card is current |  |                 |
| Corrective Action:        |                                               |  | Date:           |
| Type: Plunger Lift        | # 1                                           |  |                 |
| Comment:                  |                                               |  |                 |
| Corrective Action:        |                                               |  | Date:           |
| Type: Ancillary equipment | # 3                                           |  |                 |

|                                                  |     |       |
|--------------------------------------------------|-----|-------|
| Comment: Automation array and two ECD scrubbers  |     | Date: |
| Corrective Action:                               |     | Date: |
| Type: Bird Protectors                            | # 2 |       |
| Comment:                                         |     |       |
| Corrective Action:                               |     | Date: |
| Type: Horizontal Heated Separator                | # 1 |       |
| Comment:                                         |     |       |
| Corrective Action:                               |     | Date: |
| Type: Bradenhead                                 | # 1 |       |
| Comment: Bradenhead valve is exposed at surface. |     |       |
| Corrective Action:                               |     | Date: |
| Type: Emission Control Device                    | # 1 |       |
| Comment:                                         |     |       |
| Corrective Action:                               |     | Date: |

**Tanks and Berms:**

| Contents           | # | Capacity | Type           | Tank ID | SE GPS |
|--------------------|---|----------|----------------|---------|--------|
| PRODUCED WATER     | 1 | 100 BBLs | PBV FIBERGLASS |         | ,      |
| Comment: Anchored  |   |          |                |         |        |
| Corrective Action: |   |          |                |         | Date:  |

Paint

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

Berms

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CRUDE OIL          | 1 | OTHER    | STEEL AST |         | ,      |
| Comment: 315 bbls  |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

Paint

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|------|----------|---------------------|---------------------|-------------|
|      |          |                     |                     |             |

|                    |          |                  |                 |          |  |
|--------------------|----------|------------------|-----------------|----------|--|
| Metal              | Adequate | Walls Sufficient | Base Sufficient | Adequate |  |
| Comment:           |          |                  |                 |          |  |
| Corrective Action: |          |                  |                 | Date:    |  |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**

Facility ID: 242908 Type: WELL API Number: 123-10699 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL                                                                                                                                                                 |
|--------------|-------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 697009149    | Photos      | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6479868">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6479868</a> |