

Prospect Energy - ECMC Inspection Photos
Location: PW Injection Line between MSSU 3-6 & 30-7 Flowline Release
Spill ID #485394 Date 03/20/2024



Signage at MSSU 30-7 well



Excavation at point of release. Off location flowline pipe exposed; 2" OD Sch 80 Carbon Steel pipe with external coating (damaged in areas). Pipe failure section cut out for inspection; cut pipe ends collared and bullplugged.

Prospect Energy - ECMC Inspection Photos
Location: PW Injection Line between MSSU 3-6 & 30-7 Flowline Release
Spill ID #485394 Date 03/20/2024



Hole identified on outside of flowline pipe; 6'Oclock position. External coating damage in area of failure.



Flowline pipe cut in half for internal inspection. Black scale/sludge deposits can be seen on inside of pipe. (2) localized corrosion pits can be seen inside the pipe (left); one of the pits resulted in the hole in pipe.