

## Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE 1-13 (RB1) Pad

Location #: 334637



Photo # 975 From entrance to location



Photo # 976 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE 1-13 (RB1) Pad

Location #: 334637



Photo # 977 Location



Photo # 978 Location



## Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE 1-13 (RB1) Pad

Location #: 334637



Photo # 979 Location



Photo # 980 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE 1-13 (RB1) Pad

Location #: 334637




Photo # 981 Tank battery sign lacks required information



Photo # 982 Open ended load line

## Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE 1-13 (RB1) Pad

Location #: 334637



Mar 21, 2024 at 12:51:12 PM  
CO

**Photo # 983 PRV vent line lacks cap/does not comply with CECMC pressure safety device rules**



Mar 21, 2024 at 12:51:24 PM  
CO

**Photo # 984 PRV vent line lacks cap/does not comply with CECMC pressure safety device rules**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE 1-13 (RB1) Pad

Location #: 334637



Photo # 985 Unmarked deadman



Photo # 986 Same unmarked deadman from a different angle

## Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE 1-13 (RB1) Pad

Location #: 334637



**Photo # 987 Methanol tank improperly labeled/lacks required information**



**Photo # 988 Methanol tank improperly labeled/lacks required information**