

Interim Reclamation and Stormwater Inspection

March 19, 2024

Operator: Arch Oil & Gas LLC- #10528

Location ID: 317921

Inspection Document #: 709400996

Weld County, CO

SENW Section 18 T2N R63W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Cuykendall-Lauck #2
Location ID: 317921



Photo 1. Photo taken facing north of location sign from previous operator. New signage needed. .

Photo 2. Photo taken facing east of of wellhead.



Inspection Photos
Location Name: Cuykendall-Lauck #2
Location ID: 317921



Photo 3. Photo taken facing south of stained soil under pumpjack engine.



Photo 4. Photo taken facing northwest of interim reclamation area, Canada thistle is present.

Inspection Photos
Location Name: Cuykendall-Lauck #2
Location ID: 317921



Photo 5. Photo taken facing west of tank battery.



Photo 6. Photo taken facing south of stained soil under tank loadout pipe connection.



Inspection Photos
Location Name: Cuykendall-Lauck #2
Location ID: 317921



Photo 7. Photo taken facing south of interim reclamation area.

Photo 8. Photo taken facing west of interim reclamation area.

Inspection Photos
Location Name: Cuykendall-Lauck #2
Location ID: 317921




Photo 9. Photo taken facing north of interim reclamation area and mowed vegetation around equipment.

Photo 10. Photo taken facing west of interim reclamation area and weeds (canada thistle).