

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/19/2024

Submitted Date:

03/26/2024

Document Number:

709400996

**FIELD INSPECTION FORM**Loc ID 317921 Inspector Name: WOLD, REED On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10528

Name of Operator: ARCH OIL &amp; GAS LLC

Address: 16400 DALLAS PARKWAY SUITE 305

City: DALLAS State: TX Zip: 75248

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Browning, Jeff	940-391-7210	jbrowning@matthewssouthwest.com	All inspections
		jbrowning@archog.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240185	WELL	SI	03/01/2020	OW	123-07973	CUYKENDALL-LAUCK 2	RI
317921	LOCATION	AC			-	CUYKENDALL-LAUCK-62N63W 18SEW	RI

**General Comment:**

This is an interim and stormwater inspection for well and associated tank battery on site. Corrective actions observed during inspection include stained soil on well and tank battery pad, weeds (canada thistle), and missing correct operator signage.

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Location signage on tank battery and well head are for the previous owner, Arch Oil and Gas is needed.		
Corrective Action:	Comply with rule 605.d. signage	Date:	04/03/2024

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Failure to control and manage weeds to prevent weed waste and prevent the spread of seeds onto adjacent lands.		
Corrective Action:	Comply with Rule 606.c. weeds	Date:	04/08/2024

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		
	Tank	<= 1 bbl		
Comment:	Stained soil under tank load out valves in tank battery and stained soil under pumpjack engine.			
Corrective Action:	Comply with rule 912. spills		Date:	04/02/2024

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	240185	Type:	WELL	API Number:	123-07973	Status:	SI	Insp. Status:	RI
Facility ID:	317921	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	RI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
709400997	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6481465">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6481465</a>