

Caerus Piceance LLC
Piceance creek Unit-62S97W 10SESE
Location ID: 335696



Inadequate wildlife protection



Replace label

Caerus Piceance LLC
Piceance creek Unit-62S97W 10SESE
Location ID: 335696



When replaced additional information is required



Unmarked anchor

Caerus Piceance LLC
Piceance creek Unit-62S97W 10SESE
Location ID: 335696



Incorrect signage



Label needs replaced

Caerus Piceance LLC
Piceance creek Unit-62S97W 10SESE
Location ID: 335696



No rain protection



Debris

Caerus Piceance LLC
Piceance creek Unit-62S97W 10SESE
Location ID: 335696



Debris




Debris

Caerus Piceance LLC
Piceance creek Unit-62S97W 10SESE
Location ID: 335696




Debris. Hose hanging over flowline.



Debris

Caerus Piceance LLC
Piceance creek Unit-62S97W 10SESE
Location ID: 335696



Debris



Debris

Caerus Piceance LLC
Piceance creek Unit-62S97W 10SESE
Location ID: 335696



Production facility from Northeast corner



Production facility from Northwest corner

Caerus Piceance LLC
Piceance creek Unit-62S97W 10SESE
Location ID: 335696



Well pad from Northwest corner



Well pad from Southwest corner

Caerus Piceance LLC
Piceance creek Unit-62S97W 10SESE
Location ID: 335696



Well pad from Southeast corner



Well pad from Northeast corner