

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/19/2024

Submitted Date:

03/19/2024

Document Number:

714200815

FIELD INSPECTION FORM

Loc ID 332862 Inspector Name: Santistevan, Brittani On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 11 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		cogcc@kpk.com	All Inspections
Sanchez, Chris		chris.sanchez@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240882	WELL	PR	06/01/2023	GW	123-08670	MUSICK-MCCLINTOCK 1	SI

General Comment:

[THIS IS A WELLHEAD/BATTERY INSPECTION.](#)

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Signage appears to be faded. Recommend replacing.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	No capacity/contents displayed on one tank, no signage (capacity, contents, nfpa) displayed at other tank. See attached photos.		
Corrective Action:	Comply with Rule 605.h.	Date:	04/19/2024
Type	BATTERY		
Comment:	signage appears to be faded. recommend replacing.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	Tank appears to be leaking. See attached photo.		
Corrective Action:	Comply with Rule 609.b. Contact ECMC enviromental.	Date:	04/19/2024
Type	WEEDS		
Comment:	Weeds/debris on various areas of location. See attached photo.		
Corrective Action:	Comply with Rule 606.	Date:	04/19/2024
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	SEPARATOR		
Comment:	wire		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	iron		
Corrective Action:		Date:	
Equipment:			
Type: Bird Protectors			corrective date
# 1			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:		Date:	

Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	OTHER	BV CONCRETE		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)	UNKNOWN	
Other (Capacity)	UNKNOWN	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)	UNKNOWN	

Other (Capacity) UNKNOWN	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO				
Comment:					
Corrective Action:				Date:	

Flaring:

Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities

Facility ID: 240882 Type: WELL API Number: 123-08670 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary WEATHER CONDITIONS: sunny, dry ground. On Tuesday, March 19, 2024 at approximately 1100, I, Inspector Brittani Santistevan, conducted an on-site inspection at MUSICK-MCCLINTOCK #1 (KP Kauffman Company Inc), at location ID: 332862 in WELD COUNTY Colorado. While there, I observed a shut in facility. During this inspection the following possible compliance issues were observed: 1. There is weeds/debris on various areas of location. Comply with Rule 606. (Corrective Action Date: April 19, 2024) See attached photo #4-7, 10-15. 2. No capacity/contents displayed on one tank. No signage (Capacity, contents, NFPA) displayed at another tank. Install sign to comply with Rule 605.h. (Corrective Action Date: April 19, 2024) See attached photo #9, 13. 3. Tank appears to be leaking fluid inside containment. Comply with Rule 609.b. Contact ECMC area environmental personnel. (Corrective Action Date: April 19, 2024) See attached photo #7.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	03/19/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403725621	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6474383
714200816	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6474380