

Inspection Photos

API: 017-06629

Operator: **WILLIFORD ENERGY COMPANY**

Inspection Date: 3/26/2024

County: Cheyenne



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east along the access road. Vehicles are causing unnecessary disturbance driving outside of the access road due to stormwater pooling on the road. The access road must be maintained and shall not drive outside of the access road boundary.



Inspection Photos



Photo 2. There is oil leaking out of the wellhead that must be controlled and cleaned up.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 3. There is a panel laying on the ground that needs to be removed. There is oily fluids leaking out of the pumpjack at red arrow.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 4. Facing southwest toward the engine compressor. There is oil saturated soils that have leaked out of the engine compressor. The leak must be controlled and impacted soils removed.



Inspection Photos



Photo 5. View of inside the shed shows oil saturated soils from the leaking engine. There is oil containers tipped over and no secondary containment.



Inspection Photos



Photo 6. The well name doesn't appear to match the name of the well Rhoades 6-32.

