

Inspection Photos
Location Name: Community #1 Facility
Location ID: 319888



Photo 1 entrance to facility. Tracking pad impacted with sediment and being carried onto city street.



Photo 2 tracking pad in need of maintenance.

Inspection Photos
Location Name: Community #1 Facility
Location ID: 319888



Photo 3 TNK BTRY



Photo 4 ECD

Inspection Photos
Location Name: Community #1 Facility
Location ID: 319888



Photo 5 unused equipment port a potty



Photo 6 Well head

Inspection Photos
Location Name: Community #1 Facility
Location ID: 319888



Photo 7 unused equipment (fencing)



Photo 8 location not draining properly due to improper BMP's