

Inspection Photos
Location Name: Nessu 15
Location ID: 317831



Photo 1 Location.



Photo 2 Wellsite.

Inspection Photos
Location Name: Nessu 15
Location ID: 317831



Energy & Carbon Management Commission
48° 7' 18" N 104° 47' 51" W, 4824 16, 185"
03/27/2024 14:31:18



Energy & Carbon Management Commission
48° 7' 18" N 104° 47' 51" W, 4824 16, 185"
03/27/2024 14:31:47

Photo 3 Debris(dead vegetation) around the WH, Land owner has fence posts stacked by the WH.

Photo 4 WH sign.

Inspection Photos
Location Name: Nessu 15
Location ID: 317831



Photo 5 Ancillary equip.



Photo 6 Debris(dead vegetation) around the Wellsite.

Inspection Photos
Location Name: Nessu 15
Location ID: 317831



Photo 7 Land owner has AG gates stacked around the wellsite.



Photo 8 Land owner has AG gates stacked around the wellsite.