

Inspection Photos

API: 017-06622

Operator: **WILLIFORD ENERGY COMPANY**

Inspection Date: 3/26/2024

County: Cheyenne



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east along the access road. Vehicles are causing unnecessary disturbance driving outside of the access road due to stormwater pooling on the road. The access road must be maintained and shall not drive outside of the access road boundary.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:017-06622 | Date: 3/26/2024

Inspection Photos



Photo 2. Facing east at the wellsite. There is oily waste pooled up on the surface shown at red arrow.



Inspection Photos



Photo 3. There is oily wasted shown at red arrow that must be cleaned up and properly disposed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 4. Facing east toward the well. There is signs the a spill occurred at the wellsite that spread out west and south of the well with an undetermined amount spilled which will require a spill report.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:017-06622 | Date: 3/26/2024

Inspection Photos



Photo 5. There is a spill that occurred at the wellhead with an undetermined amount spilled which will require a spill report.



Inspection Photos



Photo 6. There are chemical barrels with no secondary containment. There are blackened stain soils around the equipment.



Inspection Photos



Photo 7. There is oil coming out of the exhaust pipe which is staining the soil and needs to be cleaned up.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API:017-06622 | Date: 3/26/2024

Inspection Photos



Photo 8. Facing south along the access road. Vehicles are causing unnecessary disturbance driving outside of the access road due to stormwater pooling on the road. The access road must be maintained and shall not drive outside of the access road boundary.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:017-06622 | Date: 3/26/2024

Inspection Photos



Photo 9. The cattleguard at the beginning of the access road is filled in with sediment and needs to be cleaned out and maintained.

